


O I P E I A P S
OCT 07 2005
P A T E N T & T R A D E M A R K O F F I C E

Appn. No. 10/501,870
Reply to Office Action of June 7, 2005
REPLACEMENT SHEET



Start Position. Mold Located
on Bush, Probe Up

Fig. 1